Weathertzatton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/40004CL1036
Work Order Type: Weatherization
Audit Name: 40004CL1036

CLIENT INFORMATION

Client Name: Address:

Client ID: 40004CL1036

Alt. Client ID: MONTGOMERY

<u>AGENCY INFORMATION</u>

Agency: Clarksville-Montgomery CCAA

Agency Phone: (931) 648-5774

Address: (PO Box 487) 350 Pageant Lane, Suite 307

Fax: (931) 648-5784

Agency Contact: CARLISLE, RON Work Phone:

Cell Phone: (423) 736-0678

Email Address: ronald.carlisle@gmail.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

912 SQ. FT. RANCH WITH METAL SIDING BUILT ON A CRAWL SPACE IN 1960

ALL WORK TO BE DONE IN ACCORDANCE WITH THE TENNESSEE WEATHERIZATION FIELD GUIDE

CONTRACTOR IS RESPONSIBLE TO VERIFY DIMENSIONS AND SCOPE OF WORK PRIOR TO BID

CERTIFIED FIRM/RENOVATOR REQUIRED

PRE-WORK BLOWER DOOR 2236 @-50 POST WORK TARGET 1600 @-50

AUDIT DATE 3-27-12

Client Name:
Client ID: 40004CL1036
Alt. Client ID: MONTGOMERY

Work Order (Bid Form)
Work Order Name: WO/40004CL1036

DOE Weatherization Assistant Version 8.6.0

Page 1 of 4

Report Run On: 4/1/2012

Measure	1 Infilt	ration Redctn			Componen	ts			Inspected
Commen		JRELY SECURE THE P PERIMETER	LUMBING	ACCE	SS WITH S	CREWS	-		
		_ACE 3 MISSING OR BF WINDOWS	ROKEN W	INDOV	W LOCKS -	DOUBLE	HUNG	i	
	3. CAUI	LK THE TUB TO THE SU	JRROUNI)					
	4. INST	ALL W/S AND SWEEP (ON THE F	RONT					
					Estimated	<u> </u>		Actual	
# Material	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscella	neous Su	Infiltration Reduction	Each	1					
I1 Labor		LKABOR	Hour						
Other Deta	nil								
				Measur	e Sub Total:			Sub Total:	
Field No	tes:								

Report Run On: 4/1/2012

N	<i>leasur</i> e 2 Lig	hting Retrofits			Componen	ts L1		-	Inspected	
Co	omment									
					Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Lighting	Compact Fl 13 Watt	Each Lamp	6						
2	Labor	Compact Fl 13 Watt	Each Lamp	6						
O	ther Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
N	Measure 3 Att	tic Ins. R-30			Componen	ts A1,A2		ı	Inspected	
Co	omment NO BA	AFFLES REQUIRED			•					
	INSTA	LL AN ENERGY LID ON A	ATTIC AC	CESS	W/S AND IN	SULATE				
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	500						
2	Labor	Attic Insulation -	SqFt	500						
		Cellulose, Blown - R-30								
3	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	419						
4	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	419						
O	ther Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:			Measur	e Sub Total:		,	Sub Total:		
	Field Notes:			Measur	e Sub Total:			Sub Total:		

Client Name: Client ID: 40004CL1036 Alt. Client ID: MONTGOMERY Work Order (Bid Form)
Work Order Name: WO/40004CL1036

DOE Weatherization Assistant Version 8.6.0 Page 3 of 4

Report Run On: 4/1/2012

Measure 4	Vapor Barrier Needed (Basement/Crawlspace)	Components
Comment IN	STALL 6 MIL BLACK POLY \	/APOR BARRIER GROUND COVER.

				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety	Basement / crawlspace vapor barrier	SqFt	1					
•	Labor	Labor	SqFt	1					
C	ther Detail						1		
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:								

Work Order Grand Total:

Client Name: Client ID: 40004CL1036 Alt. Client ID: MONTGOMERY

Work Order (Bid Form)

DOE Weatherization Assistant Version 8.6.0 Page 4 of 4

Grand Total:

Inspected